

Corner I.D. # 118T

MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE


Section 9, Township 9N, Range 2W,**Monument Description & Remarks:** 2-1/2" Aluminum Monument, 30" long, set 0.1' below grade.(This monument is not a PLSS corner. It was set as part of a Geodetic Control Survey.)

8/22/2016, Rachel Savich Oser, Fbk. 48, pg. 3

Monument recovered. Cap was not attached to the rod, which was 0.4' below grade and solid in the ground.

Placed cap upside down on rod and buried.

7/24/2018, Cassidy Raley, Fbk. 52, pg. 22



I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Matthew L. Cooper
 Indiana Registered Land Surveyor No. LS20200079

COMPLETED By *Sta. Tanks*





0 50 100 200 Feet

ImageSource: 2014 Monroe County Pictometry



Office of the Monroe County Surveyor
2004 Geodetic Control Project

119 West 7th Street
Bloomington, Indiana 47404
(812) 349-2570

